



## VST 224 ID

₹ 250000

Pune, Maharashtra

### SUMMARY

<b>Brand</b>	VST	<b>Model</b>	224 ID
<b>Registration No.</b>	MH14DH3251	<b>Manufacturing Year</b>	2014
<b>HP</b>	22	<b>Hours Run</b>	840
<b>No. Of Owners</b>	1	<b>RC Book Available</b>	Yes
<b>RC Book Validity</b>	01-01-1970	<b>Finance Hypothecation</b>	No
<b>Insurance Available</b>	No	<b>Tax Paid</b>	Yes
<b>Tax Paid Till</b>	01-01-1970	<b>Fitness Certificate Available</b>	Yes
<b>Fitness Certificate Validity</b>	01-01-1970		

## INSPECTION DETAILS



### Engine

➤ Engine Noise Level	Ok
➤ Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster)	Ok
➤ Smoke Condition (White/Black/Blue/Clear)	Ok
➤ Structural Condition (Check for any damages)	Ok
➤ Check Engine Serial No. for any tampering	Ok
➤ Leakage (Oil/ Coolant/ Fuel)	Ok
➤ Engine Oil Quality (Dilution with water and fuel), check oil level	Ok
➤ Physical Condition of Radiator, check for any major fins damaged, any major soldering done	Ok
➤ Air Cleaner Physical condition & connecting hose condition	Ok
➤ Check for FIP Serial no & Intactness of Seal	Ok

---



### Transmission

➤ Structural Condition (Check for any damages)	Ok
➤ Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement	Ok
➤ Transmission oil Quality (check dilution with water)	Ok
➤ Noise during brake application	Ok
➤ Check Clutch operation (There should be smooth gear shifting during clutching)	Ok
➤ Oil Leakage	Ok
➤ Abnormal noise in transmission	Ok

---



### Hydraulics

➤ Structural Condition (Check for any damages)	Ok
➤ Oil Leakage	Ok
➤ Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump	Ok
➤ Working of Isolater valve	Ok
➤ Oil Quality( Dilution with water)	Ok

➤ Physical condition of 3 point linkage - any major damage ? **Ok**

---



## Sheet Metal

- Paint condition of Hood, Fender. Scuttle, Front grill - any major issues **Ok**
  - Check for any major Dent/ Bent and Rustiness **Ok**
  - Check for major damage to Hood/ Fender Mountings **Not Ok**
  - Note: hood not a
- 



## Electricals

- Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning **Ok**
  - Instrument cluster condition - any major issues **Ok**
  - Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues **Ok**
  - Functioning of Starter Motor (should be able to crank the engine) **Ok**
  - Functioning of Alternater (Battery charge indicator should work) **Ok**
- 



## Tractor

- Tyre Physical Condition (to check for major cut and threads and check for uneven wear) **Ok**
  - Tread Depth (at least 25%) **Ok**
  - Wheel Rim Physical condition (Check for major cracks, welds, damage) **Ok**
  - Steering Box (Power / Manual) & Power Cylinder (should be no leakages) **Ok**
  - Any major excess Play in Steering linkage **Ok**
  - Physical condition of Seat **Ok**
  - Mirror, Foot rest, Platform - major issues **Ok**
-