



ESCORTS 60 FT

₹ 200000

Villupuram, Tamil nadu

SUMMARY

Brand	ESCORTS	Model	60 FT
Registration No.	TN32T4462	Manufacturing Year	2006
HP	45	Hours Run	4000
No. Of Owners	1	RC Book Available	No
Finance Hypothecation	No	Insurance Available	No
Tax Paid	Not Applicable	Fitness Certificate Available	Not Applicable

INSPECTION DETAILS



Engine

- Engine Noise Level
 - Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster)
 - Smoke Condition (White/Black/Blue/Clear)
 - Structural Condition (Check for any damages)
 - Check Engine Serial No. for any tampering
 - Leakage (Oil/ Coolant/ Fuel)
 - Engine Oil Quality (Dilution with water and fuel), check oil level
 - Physical Condition of Radiator, check for any major fins damaged, any major soldering done
 - Air Cleaner Physical condition & connecting hose condition
 - Check for FIP Serial no & Intactness of Seal
-



Transmission

- Structural Condition (Check for any damages)
 - Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement
 - Transmission oil Quality (check dilution with water)
 - Noise during brake application
 - Check Clutch operation (There should be smooth gear shifting during clutching)
 - Oil Leakage
 - Abnormal noise in transmission
-



Hydraulics

- Structural Condition (Check for any damages)
- Oil Leakage
- Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump
- Working of Isolater valve
- Oil Quality(Dilution with water)

- Physical condition of 3 point linkage - any major damage ?
-



Sheet Metal

- Paint condition of Hood, Fender, Scuttle, Front grill - any major issues
 - Check for any major Dent/ Bent and Rustiness
 - Check for major damage to Hood/ Fender Mountings
-



Electricals

- Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning
 - Instrument cluster condition - any major issues
 - Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues
 - Functioning of Starter Motor (should be able to crank the engine)
 - Functioning of Alternater (Battery charge indicator should work)
-



Tractor

- Tyre Physical Condition (to check for major cut and threads and check for uneven wear)
 - Tread Depth (at least 25%)
 - Wheel Rim Physical condition (Check for major cracks, welds, damage)
 - Steering Box (Power / Manual) & Power Cylinder (should be no leakages)
 - Any major excess Play in Steering linkage
 - Physical condition of Seat
 - Mirror, Foot rest, Platform - major issues
-