



## EICHER 5660 SUPER DI

₹ 2147483647

Shivamogga, Karnataka

### SUMMARY

<b>Brand</b>	EICHER	<b>Model</b>	5660 SUPER DI
<b>Registration No.</b>	KA14C0430	<b>Manufacturing Year</b>	2014
<b>HP</b>	55	<b>Hours Run</b>	2896
<b>No. Of Owners</b>	3	<b>RC Book Available</b>	Yes
<b>RC Book Validity</b>	01-01-1970	<b>Finance Hypothecation</b>	No
<b>Insurance Available</b>	No	<b>Tax Paid</b>	Not Applicable
<b>Fitness Certificate Available</b>	Not Applicable		

## INSPECTION DETAILS



### Engine

- Engine Noise Level
  - Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster)
  - Smoke Condition (White/Black/Blue/Clear)
  - Structural Condition (Check for any damages)
  - Check Engine Serial No. for any tampering
  - Leakage (Oil/ Coolant/ Fuel)
  - Engine Oil Quality (Dilution with water and fuel), check oil level
  - Physical Condition of Radiator, check for any major fins damaged, any major soldering done
  - Air Cleaner Physical condition & connecting hose condition
  - Check for FIP Serial no & Intactness of Seal
- 



### Transmission

- Structural Condition (Check for any damages)
  - Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement
  - Transmission oil Quality (check dilution with water)
  - Noise during brake application
  - Check Clutch operation (There should be smooth gear shifting during clutching)
  - Oil Leakage
  - Abnormal noise in transmission
- 



### Hydraulics

- Structural Condition (Check for any damages)
- Oil Leakage
- Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump
- Working of Isolater valve
- Oil Quality( Dilution with water)

- Physical condition of 3 point linkage - any major damage ?
- 



## Sheet Metal

- Paint condition of Hood, Fender, Scuttle, Front grill - any major issues
  - Check for any major Dent/ Bent and Rustiness
  - Check for major damage to Hood/ Fender Mountings
- 



## Electricals

- Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning
  - Instrument cluster condition - any major issues
  - Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues
  - Functioning of Starter Motor (should be able to crank the engine)
  - Functioning of Alternater (Battery charge indicator should work)
- 



## Tractor

- Tyre Physical Condition (to check for major cut and threads and check for uneven wear)
  - Tread Depth (at least 25%)
  - Wheel Rim Physical condition (Check for major cracks, welds, damage)
  - Steering Box (Power / Manual) & Power Cylinder (should be no leakages)
  - Any major excess Play in Steering linkage
  - Physical condition of Seat
  - Mirror, Foot rest, Platform - major issues
-