



ACE 350 DI

₹ 110000

Bardhaman, West bengal

SUMMARY

Brand	ACE	Model	350 DI
Registration No.	WB53B3416	Manufacturing Year	2013
HP	39	Hours Run	5000
No. Of Owners	1	RC Book Available	Yes
RC Book Validity	23-12-2015	Finance Hypothecation	No
Insurance Available	No	Tax Paid	Not Applicable
Fitness Certificate Available	Not Applicable		

INSPECTION DETAILS



Engine

- > Engine Noise Level **Ok**
 - > Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster) **Ok**
 - > Smoke Condition (White/Black/Blue/Clear) **Ok**
 - > Structural Condition (Check for any damages) **Ok**
 - > Check Engine Serial No. for any tampering **Ok**
 - > Leakage (Oil/ Coolant/ Fuel) **Ok**
 - > Engine Oil Quality (Dilution with water and fuel), check oil level **Ok**
 - > Physical Condition of Radiator, check for any major fins damaged, any major soldering done **Ok**
 - > Air Cleaner Physical condition & connecting hose condition **Ok**
 - > Check for FIP Serial no & Intactness of Seal **Ok**
-



Transmission

- > Structural Condition (Check for any damages) **Ok**
 - > Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement **Ok**
 - > Transmission oil Quality (check dilution with water) **Ok**
 - > Noise during brake application **Ok**
 - > Check Clutch operation (There should be smooth gear shifting during clutching) **Ok**
 - > Oil Leakage **Ok**
 - > Abnormal noise in transmission **Ok**
-



Hydraulics

- > Structural Condition (Check for any damages) **Ok**
- > Oil Leakage **Ok**
- > Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump **Ok**
- > Working of Isolater valve **Ok**
- > Oil Quality(Dilution with water) **Ok**

> Physical condition of 3 point linkage - any major damage ? **Ok**



Sheet Metal

- > Paint condition of Hood, Fender. Scuttle, Front grill - any major issues **Ok**
 - > Check for any major Dent/ Bent and Rustiness **Ok**
 - > Check for major damage to Hood/ Fender Mountings **Ok**
-



Electricals

- > Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning **Ok**
 - > Instrument cluster condition - any major issues **Ok**
 - > Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues **Ok**
 - > Functioning of Starter Motor (should be able to crank the engine) **Ok**
 - > Functioning of Alternater (Battery charge indicator should work) **Ok**
-



Tractor

- > Tyre Physical Condition (to check for major cut and threads and check for uneven wear) **Ok**
 - > Tread Depth (at least 25%) **Ok**
 - > Wheel Rim Physical condition (Check for major cracks, welds, damage) **Ok**
 - > Steering Box (Power / Manual) & Power Cylinder (should be no leakages) **Ok**
 - > Any major excess Play in Steering linkage **Ok**
 - > Physical condition of Seat **Ok**
 - > Mirror, Foot rest, Platform - major issues **Ok**
-