



MAHINDRA 575 DI BHOOMIPUTRA

Bardhaman, West bengal

SUMMARY

Brand	MAHINDRA	Model	575 DI BHOOMIPUTRA
Registration No.	WB453144	Manufacturing Year	2017
HP	45	Hours Run	4600
No. Of Owners	1	RC Book Available	Yes
RC Book Validity	18-01-2019	Finance Hypothecation	No
Insurance Available	No	Tax Paid	Not Applicable
Fitness Certificate Available	Not Applicable		

INSPECTION DETAILS



Engine

> Engine Noise Level	Ok
Minimium Safe engine Oil presssure (check low oil pressure indicator on instrument cluster)	Ok
> Smoke Condition (White/Black/Blue/Clear)	Ok
> Structural Condition (Check for any damages)	Ok
Check Engine Serial No. for any tampering	Ok
Leakage (Oil/ Coolant/ Fuel)	Ok
Engine Oil Quality (Dilution with water and fuel), check oil level	Ok
> Physical Condition of Radiator, check for any major fins damaged, any major soldering done	Ok
> Air Cleaner Physical condition & connecting hose condition	Ok
> Check for FIP Serial no & Intactness of Seal	Ok
 Check Engine Serial No. for any tampering Leakage (Oil/ Coolant/ Fuel) Engine Oil Quality (Dilution with water and fuel), check oil level Physical Condition of Radiator, check for any major fins damaged, any major soldering done Air Cleaner Physical condition & connecting hose condition 	Ok Ok Ok Ok

<u>چ</u>

Transmission

> Structural Condition (Check for any damages)	Ok
> Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement	Ok
Transmission oil Quality (check dilution with water)	Ok
> Noise during brake application	Ok
> Check Clutch operation (There should be smooth gear shifting during clutching)	Ok
> Oil Leakage	Ok
> Abnormal noise in transmission	Ok



Hydraulics

>	Structural Condition (Check for any damages)	Ok
>	Oil Leakage	Ok
>	Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump	Ok
>	Working of Isolater valve	Ok
>	Oil Quality(Dilution with water)	Ok



Sheet Metal

)	Paint condition of Hood, Fender. Scuttle, Front grill - any major issues	Ok
	Check for any major Dent/ Bent and Rustiness	Ok
	Check for major damage to Hood/ Fender Mountings	Ok



Electricals

> Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning	Ok
> Instrument cluster condition - any major issues	Ok
> Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues	Ok
> Functioning of Starter Motor (should be able to crank the engine)	Ok
> Functioning of Alternater (Battery charge indicator should work)	Ok



Tractor

> Tyre Physical Condition (to check for major cut and threads and check for uneven wea	or) Ok
Tread Depth (at least 25%)	Ok
Wheel Rim Physical condition (Check for major cracks, welds, damage)	Ok
Steering Box (Power / Manual) & Power Cylinder (should be no leakages)	Ok
> Any major excess Play in Steering linkage	Ok
> Physical condition of Seat	Ok
Mirror, Foot rest, Platform - major issues	Ok