



TAFE 241 DI ₹ 300000

Bijnor, Uttar pradesh

SUMMARY

| Brand | TAFE | Model | 241 DI |
|-------------------------------|----------------|-----------------------|--------|
| Registration No. | up20v5419 | Manufacturing Year | 2010 |
| HP | 30 | Hours Run | 3204 |
| No. Of Owners | 1 | RC Book Available | Yes |
| RC Book Validity | 01-01-1970 | Finance Hypothecation | No |
| Insurance Available | Not Applicable | Tax Paid | No |
| Fitness Certificate Available | No | | |

INSPECTION DETAILS



Engine

| Ok |
|----|
| Ok |
| |



Transmission

- > Structural Condition (Check for any damages)
- > Gear Engagement (no slippage, Smoothly operating or not), PTO engagement
- Transmission oil Quality (check dilution with water)
- > Noise during brake application
- > Check Clutch operation (There should be smooth gear shifting during clutching)
- > Oil Leakage
- > Abnormal noise in transmission



Hydraulics

- > Structural Condition (Check for any damages)
- > Oil Leakage
- > Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump
- > Working of Isolater valve
- > Oil Quality(Dilution with water)



Sheet Metal

- Paint condition of Hood, Fender. Scuttle, Front grill any major issues
- > Check for any major Dent/ Bent and Rustiness
- > Check for major damage to Hood/ Fender Mountings



Electricals

- Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning
- > Instrument cluster condition any major issues
- > Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) any major issues
- > Functioning of Starter Motor (should be able to crank the engine)
- > Functioning of Alternater (Battery charge indicator should work)



Tractor

- > Tyre Physical Condition (to check for major cut and threads and check for uneven wear)
- > Tread Depth (at least 25%)
- Wheel Rim Physical condition (Check for major cracks, welds, damage)
- Steering Box (Power / Manual) & Power Cylinder (should be no leakages)
- Any major excess Play in Steering linkage
- > Physical condition of Seat
- Mirror, Foot rest, Platform major issues