



## SONALIKA 740 DI III

₹ 290000

Nalgonda, Telangana

### SUMMARY

|                                      |                |                              |                |
|--------------------------------------|----------------|------------------------------|----------------|
| <b>Brand</b>                         | SONALIKA       | <b>Model</b>                 | 740 DI III     |
| <b>Registration No.</b>              | TS05EL8520     | <b>Manufacturing Year</b>    | 2015           |
| <b>HP</b>                            | 40             | <b>Hours Run</b>             | 2500           |
| <b>No. Of Owners</b>                 | 1              | <b>RC Book Available</b>     | Yes            |
| <b>RC Book Validity</b>              | 01-01-1970     | <b>Finance Hypothecation</b> | No             |
| <b>Insurance Available</b>           | No             | <b>Tax Paid</b>              | Not Applicable |
| <b>Fitness Certificate Available</b> | Not Applicable |                              |                |

## INSPECTION DETAILS



### Engine

|  |    |
|--|----|
| ➤ Engine Noise Level   | Ok |
| ➤ Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster)  | Ok |
| ➤ Smoke Condition (White/Black/Blue/Clear)   | Ok |
| ➤ Structural Condition (Check for any damages)   | Ok |
| ➤ Check Engine Serial No. for any tampering  | Ok |
| ➤ Leakage (Oil/ Coolant/ Fuel)   | Ok |
| ➤ Engine Oil Quality (Dilution with water and fuel), check oil level                         | Ok |
| ➤ Physical Condition of Radiator, check for any major fins damaged, any major soldering done | Ok |
| ➤ Air Cleaner Physical condition & connecting hose condition                                 | Ok |
| ➤ Check for FIP Serial no & Intactness of Seal   | Ok |

---



### Transmission

|  |    |
|--|----|
| ➤ Structural Condition (Check for any damages)                                   | Ok |
| ➤ Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement     | Ok |
| ➤ Transmission oil Quality (check dilution with water)                           | Ok |
| ➤ Noise during brake application   | Ok |
| ➤ Check Clutch operation (There should be smooth gear shifting during clutching) | Ok |
| ➤ Oil Leakage  | Ok |
| ➤ Abnormal noise in transmission   | Ok |

---



### Hydraulics

|  |    |
|--|----|
| ➤ Structural Condition (Check for any damages)   | Ok |
| ➤ Oil Leakage  | Ok |
| ➤ Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump | Ok |
| ➤ Working of Isolater valve  | Ok |
| ➤ Oil Quality( Dilution with water)  | Ok |

➤ Physical condition of 3 point linkage - any major damage ? **Ok**

---



## Sheet Metal

➤ Paint condition of Hood, Fender. Scuttle, Front grill - any major issues **Ok**

➤ Check for any major Dent/ Bent and Rustiness **Ok**

➤ Check for major damage to Hood/ Fender Mountings **Ok**

---



## Electricals

➤ Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning **Ok**

➤ Instrument cluster condition - any major issues **Ok**

➤ Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues **Ok**

➤ Functioning of Starter Motor (should be able to crank the engine) **Ok**

➤ Functioning of Alternater (Battery charge indicator should work) **Ok**

---



## Tractor

➤ Tyre Physical Condition (to check for major cut and threads and check for uneven wear) **Ok**

➤ Tread Depth (at least 25%) **Ok**

➤ Wheel Rim Physical condition (Check for major cracks, welds, damage) **Ok**

➤ Steering Box (Power / Manual) & Power Cylinder (should be no leakages) **Ok**

➤ Any major excess Play in Steering linkage **Ok**

➤ Physical condition of Seat **Ok**

➤ Mirror, Foot rest, Platform - major issues **Ok**

---