



MAHINDRA 475 DI BHOOMIPUTRA

₹ 130000

Nalgonda, Telangana

SUMMARY

| | | | |
|--------------------------------------|----------------|------------------------------|--------------------|
| Brand | MAHINDRA | Model | 475 DI BHOOMIPUTRA |
| Registration No. | ap24r7521 | Manufacturing Year | 2007 |
| HP | 42 | Hours Run | 6050 |
| No. Of Owners | 1 | RC Book Available | Yes |
| RC Book Validity | 01-01-1970 | Finance Hypothecation | No |
| Insurance Available | No | Tax Paid | Not Applicable |
| Fitness Certificate Available | Not Applicable | | |

INSPECTION DETAILS



Engine

| | |
|--|----|
| ➤ Engine Noise Level | Ok |
| ➤ Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster) | Ok |
| ➤ Smoke Condition (White/Black/Blue/Clear) | Ok |
| ➤ Structural Condition (Check for any damages) | Ok |
| ➤ Check Engine Serial No. for any tampering | Ok |
| ➤ Leakage (Oil/ Coolant/ Fuel) | Ok |
| ➤ Engine Oil Quality (Dilution with water and fuel), check oil level | Ok |
| ➤ Physical Condition of Radiator, check for any major fins damaged, any major soldering done | Ok |
| ➤ Air Cleaner Physical condition & connecting hose condition | Ok |
| ➤ Check for FIP Serial no & Intactness of Seal | Ok |



Transmission

| | |
|--|----|
| ➤ Structural Condition (Check for any damages) | Ok |
| ➤ Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement | Ok |
| ➤ Transmission oil Quality (check dilution with water) | Ok |
| ➤ Noise during brake application | Ok |
| ➤ Check Clutch operation (There should be smooth gear shifting during clutching) | Ok |
| ➤ Oil Leakage | Ok |
| ➤ Abnormal noise in transmission | Ok |



Hydraulics

| | |
|--|----|
| ➤ Structural Condition (Check for any damages) | Ok |
| ➤ Oil Leakage | Ok |
| ➤ Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump | Ok |
| ➤ Working of Isolater valve | Ok |
| ➤ Oil Quality(Dilution with water) | Ok |

➤ Physical condition of 3 point linkage - any major damage ? **Ok**



Sheet Metal

➤ Paint condition of Hood, Fender. Scuttle, Front grill - any major issues **Ok**

➤ Check for any major Dent/ Bent and Rustiness **Ok**

➤ Check for major damage to Hood/ Fender Mountings **Ok**



Electricals

➤ Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning **Ok**

➤ Instrument cluster condition - any major issues **Ok**

➤ Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues **Ok**

➤ Functioning of Starter Motor (should be able to crank the engine) **Ok**

➤ Functioning of Alternater (Battery charge indicator should work) **Ok**



Tractor

➤ Tyre Physical Condition (to check for major cut and threads and check for uneven wear) **Ok**

➤ Tread Depth (at least 25%) **Ok**

➤ Wheel Rim Physical condition (Check for major cracks, welds, damage) **Ok**

➤ Steering Box (Power / Manual) & Power Cylinder (should be no leakages) **Ok**

➤ Any major excess Play in Steering linkage **Ok**

➤ Physical condition of Seat **Ok**

➤ Mirror, Foot rest, Platform - major issues **Ok**
