



MAHINDRA 265 DI BHOOMIPUTRA

₹ 125000

Bardhaman, West bengal

SUMMARY

Brand	MAHINDRA	Model	265 DI BHOOMIPUTRA
Registration No.	EB41D9654	Manufacturing Year	2009
HP	30	Hours Run	5285
No. Of Owners	1	RC Book Available	Yes
RC Book Validity	01-01-1970	Finance Hypothecation	No
Insurance Available	No	Tax Paid	Yes
Tax Paid Till	05-04-2023	Fitness Certificate Available	Yes
Fitness Certificate Validity	14-05-2018		

INSPECTION DETAILS



Engine

➤ Engine Noise Level	Ok
➤ Minimum Safe engine Oil pressure (check low oil pressure indicator on instrument cluster)	Ok
➤ Smoke Condition (White/Black/Blue/Clear)	Ok
➤ Structural Condition (Check for any damages)	Ok
➤ Check Engine Serial No. for any tampering	Ok
➤ Leakage (Oil/ Coolant/ Fuel)	Ok
➤ Engine Oil Quality (Dilution with water and fuel), check oil level	Ok
➤ Physical Condition of Radiator, check for any major fins damaged, any major soldering done	Ok
➤ Air Cleaner Physical condition & connecting hose condition	Ok
➤ Check for FIP Serial no & Intactness of Seal	Ok



Transmission

➤ Structural Condition (Check for any damages)	Ok
➤ Gear Engagement - (no slippage, Smoothly operating or not), PTO engagement	Ok
➤ Transmission oil Quality (check dilution with water)	Ok
➤ Noise during brake application	Ok
➤ Check Clutch operation (There should be smooth gear shifting during clutching)	Ok
➤ Oil Leakage	Ok
➤ Abnormal noise in transmission	Ok



Hydraulics

➤ Structural Condition (Check for any damages)	Ok
➤ Oil Leakage	Ok
➤ Check for hydraulic lifting with PC DC lever (check for jerk or lowering). Check noise from Hydraulic Pump	Ok
➤ Working of Isolater valve	Ok
➤ Oil Quality(Dilution with water)	Ok

➤ Physical condition of 3 point linkage - any major damage ? **Ok**



Sheet Metal

➤ Paint condition of Hood, Fender. Scuttle, Front grill - any major issues **Ok**

➤ Check for any major Dent/ Bent and Rustiness **Ok**

➤ Check for major damage to Hood/ Fender Mountings **Ok**



Electricals

➤ Head Lamp, Brake Light, Side Indicators, plough lamp, Hazzard Functioning **Ok**

➤ Instrument cluster condition - any major issues **Ok**

➤ Physical condition of Battery and Battery Mountings (Bracket/Support/Tray) - any major issues **Ok**

➤ Functioning of Starter Motor (should be able to crank the engine) **Ok**

➤ Functioning of Alternater (Battery charge indicator should work) **Ok**



Tractor

➤ Tyre Physical Condition (to check for major cut and threads and check for uneven wear) **Ok**

➤ Tread Depth (at least 25%) **Ok**

➤ Wheel Rim Physical condition (Check for major cracks, welds, damage) **Ok**

➤ Steering Box (Power / Manual) & Power Cylinder (should be no leakages) **Ok**

➤ Any major excess Play in Steering linkage **Ok**

➤ Physical condition of Seat **Ok**

➤ Mirror, Foot rest, Platform - major issues **Ok**
